



In This Issue:

BERARD
SINCE
1945
The Mega Transport Experts

- > The Shipyard | Tugboat Load Out
- > On The Road | Dual Lane Vessel Transport
- > Spotlight On Safety | Staying Warm

The Shipyard Tug Load Out



Job Specs

Weight:

300 Tons

Dimensions:

94'L x 28'W

Equipment Used: 12 axle lines of SPMTs, 2 powerpacks, ramps and high volume water pumps

The Berard team recently helped an Alabama shipyard with the load out and transfer of a tugboat. The team first transported the cargo through the fabrication yard and loaded it onto a waiting deck barge. It then made a water transit over to the client's dry dock where it was transferred from the deck barge to the dry dock. The team was a big help to the shipyard by assuring the project stayed on schedule. Berard has been a part of shipyard projects for decades, when they need us, we're there. Contact the Berard sales team today and see why shipyards across the nation count on us.





On The Road Dual Lane Vessel Transport



Job Specs

Weight: 660,000 lbs.

Dimensions:

213' L x 14' W x 18' H

Equipment Used:

10 axle line Faymonville DualMAX platform trailer,
(2) KW C500 prime movers,
escort vehicles, police escorts,
and bucket trucks

When this vessel needed to be transported from a fabricator in Louisiana to a Texas industrial site Berard got the call. Weighing at 320,000 lbs., the vessel required transport on 10 axles of Faymonville DualMAX dual lane platform trailers. Kenworth C500 pull and push trucks were used to power the load. Berard determined a suitable route at 280 miles for the 200' long, 18' high, and 600,000 lb. gross weight vehicle. In 2 days, the load was safely moved on time to the destination.





It's Cold Out There! Staying Warm



Winter weather can expose outdoor workers to frostbite, hypothermia, and cold stress, all of which can be fatal. It is important to know the wind chill temperature to better prepare and perform the work safely.

Follow these work practices to stay safe in cold weather:

- Know the symptoms of cold stress; reddening skin, tingling, pain, swelling, leg cramps, numbness, and blisters.
- Dress properly; wear at least three layers of loose-fitting clothing, insulated gloves and boots, and cover your head.
- Monitor your physical condition and that of your coworkers.
- Stay dry and pack extra clothes; moisture can increase heat loss from the body.
- Take frequent breaks in warm, dry areas.
- Drink warm liquids.

> Birthdays @ Berard

Happy Birthday!

Happy Birthday to These Dedicated Team Members!

**Scott Angelle
Jason Badeaux
Braedon Berard
Ashby Breaux**

**Caleb Comeaux
Lacy Comeaux
Cruz Stansbury
Kaylee Williams**